

MEMO

Project:	Alberton Wind Farm	Document No.:	Mm 007		
То:	Synergy Wind Pty Ltd	Date:	5 November 2018		
Attention:	Ms Coralie Spitnzer	Cross Reference:	Rp 002 R02 2015590ML Alberton Wind Farm noise assessment, dated 19 April 2018		
Delivery:	Email	Project No.:	2015590ML		
From:	Alex Morabito	No. Pages:	1	Attachments:	No
CC:	Bernard Stewart				
Subject:	Predicted Noise Levels - Receiver S01				

This document details predicted noise levels at a previous unidentified receiver location in the vicinity of the Alberton Wind Farm.

The predicted noise levels presented herein are based on the assessed thirty-four (34) wind turbine layout and modelling assumptions as documented in MDA report, *Alberton Wind Farm Noise Assessment*, reference, Rp 002 R02 2015590ML Alberton Wind Farm noise assessment, dated 19 April 2018.

We understand the receiver location, identified as S01, is a proposed dwelling, however was not inhabited nor habitable at the time of the planning submission. Table 1 details the receiver location coordinates.

Table 1	: Receiver	coordinates	(WGS84	Zone	55
---------	------------	-------------	--------	------	----

Receiver	Easting (m)	Northing (m)	Distance to nearest turbine (m)
S01	467322	5722563	773

The noise level predictions at receiver SO1 are provided in Table 2, for the seven (7) candidate wind turbines previously assessed for the site.

Receiver	Senvion	Siemens	Vestas	Siemens	Siemens	Gamesa	Vestas
	3.4M140	SWT 3.3-130	V136-3.45	SWT-3.15-142	SWT-3.6-130	G132-3.465	V136-3.6
S01	39.0	40.9	41.3	39.5	39.8	41.1	40.2

Table 2: Highest predicted noise levels receiver S01 - dB LA90

The predicted noise levels are above the NZS 6808:2010 base noise limit of 40 dB L_{A90} for four (4) of the seven (7) candidate wind turbines proposed for the site.

Given the margin of compliance for particular wind turbine models, and subject to the wind farm being approved, it is likely a permit requirement will require that once the final turbine selection and layout (allowing for micro-siting) are confirmed, that compliance with the relevant noise limit will also need to be reassessed.

