

Mt Buller Ski Field, Mid-station Building Extension

SEMP Appendix Vegetation Photos

Photo points



Photo 1 – Western wall of Existing Mid-station building.



Photo 2 – Western and northern walls of existing Mid-station building.



Photo 3 – Western end of Mid-station in 2007 during the removal of the Blue Bullet 2 lift. This western wall end was subsequently boarded up and the excavation backfilled to the levels seen in Photos 1 & 2.

2023 Photos



West elevation and vegetation



West elevation and vegetation



Looking north, southern trenching alignment



Looking south, southern trenching alignment



Looking south, northern trenching alignment



Looking north, northern trenching alignment